

D.C. Generator. Chapter - 1

- 1) The armature of a d.c. machine is made of ____
 - (i) silicon steel (ii) wrought iron
 - (iii) cast steel (iv) soft iron.
- 2) A 4 pole d.c. machine has ____ magnetic ckts.
 - (i) 2 (ii) 8
 - (iii) 4 (iv) none of the above.
- 3) The greatest eddy current loss occurs in the ____ of a d.c. machine.
 - (i) field poles (ii) yoke.
 - (iii) Commutating pole (iv) armature.
- 4) The commutator pitch for a Simplex Lap winding is equal to.
 - (i) number of poles of the machine.
 - (ii) pole pairs.
 - (iii) 1
 - (iv) none of the above.
- 5) In a d.c. machine, the number of commutator segments is equal to.
 - (i) number of conductors (ii) twice the number of poles.
 - (iii) number of coils (iv) none of the above.
- 6) An 8-pole Simplex lap winding will have ____ parallel path.
 - (i) 8 (ii) 4
 - (iii) 32 (iv) 16

(7) A 6-pole lap wound generator has 300 conductors. The e.m.f induced per conductor being 5V. The generated voltage of the generator is _____.

- (i) 60V.
- (ii) 150V.
- (iii) 350V.
- (iv) 250V.

(8) A shunt generator delivers 195A at a terminal p.d. of 250V. The $R_a = 0.02\Omega$, $R_{sh} = 50\Omega$. What is the value of generated emf?

- (i) 246 V.
- (ii) 270V
- (iii) 254V.
- (v) 282V.

(9) If W_c is the constant loss and R_a is the armature resistance of a d.c. generator, then load current I_L corresponding to maximum efficiency is

$$(i) I_L = \sqrt{\frac{R_a}{W_c}} \quad (ii) I_L = \frac{W_c}{\sqrt{R_a}}$$

$$(iii) I_L = \frac{R_a}{\sqrt{W_c}} \quad (\checkmark) (iv) I_L = \sqrt{\frac{W_c}{R_a}}$$

(10) From question number 8 what is the value of copper losses?

- (i) 825 W.
- (ii) 2050W.
- (iii) 1025W.
- (v) 960W.

(11) A 4 pole, lap wound d.c. shunt generator has an armature winding consisting of 220 turns each of 0.004Ω . The armature resistance is

- (i) 0.5Ω
- (ii) 1Ω
- (iii) 0.0255Ω
- (iv) 0.055Ω .

D.C. Generator. Chapter-II.

Armature Reaction and Commutation.

- 1) In a d.c. generators armature reaction is produced by
 - (i) the field current
 - (ii) ~~armature current.~~
 - (iii) both field and armature current.
 - (iv) none of the above.
- 2) Armature reaction is increased when.
 - (i) the field current increases.
 - (ii) the armature current decreases.
 - (iii) ~~the armature current increases.~~
 - (iv) none of the above.
- 3) When a d.c. generator carries no armature current.
 - (i) M.N.A coincides with G.N.A.
 - (ii) M.N.A is behind G.N.A.
 - (iii) M.N.A is ahead of G.N.A.
 - (iv) none of the above.
- 4) In order to have sparkless commutation, the brushes should be placed.
 - (i) along G.N.A
 - (ii) ~~along M.N.A.~~
 - (iii) along G.N.A or M.N.A
 - (iv) none of the above.
- 5) flux distribution due to armature reaction causes the M.N.A in a generator to,
 - (i) remain stationary
 - (ii) move in the dirⁿ of rotation.
 - (iii) move opposite to the dirⁿ of rotation.
 - (iv) none of the above.

6) In a d.c. generator the effect of armature reaction on the main pole flux is to.

- (i) reduce it
- (ii) distort it.
- (iii) both reduce and distort it.
- (iv) reverse it.

7) During commutation, the coil undergoing commutation _____ by the brush.

- (i) remains short-circuited.
- (ii) remains open-circuited.
- (iii) either (i) or (ii).
- (iv) none of the above

8) The current-time graph for ideal commutation is

- (i) a straight line
- (ii) parabola.
- (iii) hyperbola.
- (iv) none of the above

9) The commutation period is of the order of.

- (i) $\frac{1}{10}$ second.
- (ii) $\frac{1}{50}$ second.
- (iii) $\frac{1}{500}$ second.

10) The reactance voltage in a d.c. shunt generator depends upon.


- (i) armature current
- (ii) field current.
- (iii) both (i) & (ii)
- (iv) neither (i) nor (ii)

Characteristics.

- 1) The field winding of a d.c. shunt machine usually carries _____ of the rated current of the machine.
 - (i) 2% to 5%. (ii) 15% to 20%.
 - (iii) more than 20%. (iv) less than 0.5%.
- 2) D.C. machines which are subjected to abrupt changes of load are provided with:
 - (i) interpole windings (ii) compensating windings.
 - (iii) equalizers. (iv) copper brushes.
- 3) Fig. 1 shows the external characteristic of generator.

(i) Over-compounded (ii) Series.

(iii) flat-compounded (iv) shunt.



- 4) Referring to Fig. 1, the voltage drop at no. 2 is due to _____.

(i) friction

(ii) armature reaction.

(iii) field circuit. (iv) none of the above

- 5) The D.C.C. of a d.c. generator is also called its _____ characteristics.

(i) magnetic

(ii) internal.

(iii) external

(iv) performance.

6) Fig. 2 shows the external characteristics of a _____ generator.

- (i) shunt.
- (ii) flat-compounded.
- (iii) series.
- (iv) over-compounded.





Fig. 2

7) Fig. 3, curve C represents the external characteristic of a _____ generator.

- (i) compound.
- (ii) separately-excited.
- (iii) shunt
- (iv) none of the above.



8) The line representing the critical resistance of a d.c. generator _____ its O.C.L.

- (i) intersects
- (ii) runs parallel to.
- (iii) just touches
- (iv) none of the above.

9) Which of the following generator provides approximately const. voltage from no-load to full-load.

- (i) Series
- (ii) shunt.
- (iii) flat compounded
- (iv) over-compounded.

10) A shunt generator gives its greatest voltage at

- (i) no-load.
- (ii) full-load.
- (iii) half full-load
- (iv) none of the above.

1-Φ TRANSFORMER

- 1) A transformer will work on _____
a) a.c. only b) d.c. only.
c) a.c as well as d.c. d) none of the above.
- 2) The primary and secondary of a transformer are coupled _____
a) electrically. b) magnetically.
c) both (a) & (b) d) none of the above.
- 3) A transformer transfers electrical energy from primary to secondary usually with change of _____.
a) frequency b) power.
c) voltage d) time period.
- 4) Calculate the core-area required for a 1600 kVA, 6600/440V, 50Hz, single phase core-type power transformer. Assume a maximum flux density of 1.2 Wb/m² and induced voltage per turn of 30V.
a) 935 cm² b) 1100 cm²
c) 1125 cm² d) 1224 cm².
- 5) The no-load input power to a transformer is practically equal to _____ loss in the transformer.
a) iron b) copper.
c) eddy current d) none of the above.
- 6) The voltage transformation ratio is given by _____.
a) N_1/N_2 b) E_1/E_2
c) N_2/N_1 d) I_2/I_1 .
- 7) In equivalent circuit of a transformer on no-load. The element R_o accounts for _____.
a) core loss b) copper loss.
c) magnetic leakage loss d) none of the above.

D.C. motor Chapter -2

- 4) By putting controller resistance in series with the armature of a d.c. motor, we can obtain speed.
- (a) above the normal speed only.
 - (b) below the normal speed only.
 - (c) above as well as below the normal speed.
 - (d) none of the above
- 5) The difference between no-load and full-load speed of a d.c. shunt motor is of the order of.
- a) 25%
 - b) 1%
 - c) 10%
 - d) 50%

Chapt'r - 3 , Testing of D.C. ~~motor~~ machines

- 1) The efficiency of a large d.c. machine is not determined by direct loading because.
- a) it is difficult to provide means for operating a large machine under load.
 - b) it is an expensive method.
 - c) it requires the application of load.
 - d) all the above.
- 2) In a d.c. machine, windage loss is proportional to.
- a) speed
 - b) cube of speed.
 - c) square of speed
 - d) none of the above.
- 3) A d.c. machine has maximum efficiency near _____
- a) half full load
 - b) full-load.
 - c) twice the full load
 - d) No-load.

- 1) The back e.m.f in a d.c motor.
- (i) opposes the applied voltage.
 - (ii) aids the applied voltage
 - (iii) aids the armature current.
 - (iv) none of the above
- 2) The value of back e.m.f (E_b) in d.c. motor is maximum at
- (i) full load (ii) no-load.
 - (iii) half full load (iv) none of above.
- 3) A 440V d.c. shunt motor has an armature resistance of 0.8Ω and a field resistance of 200Ω . Find the back e.m.f when giving an output of 7.46 kW at 85% efficiency.
- (i) 222.4V
 - (ii) 425.8V.
 - (iii) 312.6V
 - (iv) 392.7V.
- 4) A 250V d.c. shunt motor takes a total current of 20A. Resistance of shunt field winding is 200Ω and that of armature is 0.3Ω . What is the current in the armature.
- (i) 9.65A
 - (ii) 11.25A.
 - (iii) 18.75A
 - (iv) 16.62A.
- 5) A 220V d.c. shunt motor takes a total current of 80A and runs at 800 r.p.m. Resistance of shunt field is 50Ω . and that of armature is 0.1Ω . The iron and friction losses amount to 1600W. What is the driving power of the motor.
- (i) 16050W
 - (ii) 14500W.
 - (iii) 12600W.
 - (iv) 18500W.
- 6) D.C. motor converts _____ into _____.
- (i) mechanical energy; electrical energy
 - (ii) chemical energy; electrical energy
 - (iii) solar energy; chemical energy.
 - (iv) electrical energy; Mechanical energy.

7) The shaft torque (T_{sh}) in a d.c. motor is less than total armature torque(s) because of _____ in the motor.

- (i) cu losses (ii) field losses.
~~(iii) iron and friction losses~~ (iv) none of the above.

8) Which motor has the best speed regulation.

- (i) series. (ii) Cumulatively - Compounded.
~~(iii) shunt~~ (iv) differentially - Compounded.

9) When a d.c. series motor will overspeed.

- (i) the load is increased.
(ii) the field is opened.
(iii) the armature ckt is opened.
~~(iv) load is removed.~~

10) For the same rating, which motor has the least starting torque.

- (i) compound (ii) series.
~~(iii) shunt~~ (iv) none of the above

Chapter-2, Speed control of D.C. motors.

1) A d.c. motor runs at 1725 r.p.m. at full-load and 1775 rpm at no-load. The speed regulation is.

- (i) 4.7% (ii) 2.9%
(iii) 7.6% (iv) 1.5%

2) The speed of a d.c. motor can be controlled by changing.

- (i) flux (ii) armature ckt resistance.

- (iii) applied voltage ~~(iv)~~ all of the above.

3) We can control speed by flux control method of speed control of a d.c. shunt motor.

- ~~(i)~~ above the normal speed only.
(ii) below the normal speed only.
(iii) above as well as below the normal speed.
(iv) none of the above